

Winterizing the Vac-Alert™ System

- 1) Remove the Vac-Alert™ SVRS at the union, bottom side. Take care not to misplace the O-ring that is on the underside of the unit.



- 2) Install a #8 standard rubber winter plug in the opening where the Vac-Alert™ SVRS was located.



- 3) Blow out the lines with air per normal procedure (consult your pool service provider).

- 4) After the Vac-Alert™ SVRS is removed, drain any water remaining in the unit prior to storage. To drain the unit:

- remove the vent screen



- depress the piston — once the piston is depressed, any residual water in the unit will drain out.



After draining, the piston should be reset and the vent screen re-installed prior to storage.

- 5) Store the Vac-Alert™ SVRS in the original box, or in a way that it is protected and the O-ring is not lost.
- 6) Be sure to advise the end user that the Vac-Alert™ SVRS *must be installed and tested prior to re-opening the pool/spa.*

NOTE: Winterize the pool/spa as per your pool service provider's recommendations (e.g., antifreeze, etc.), for your climate zone.
Vac-Alert™ assumes no liability for pool/spa winterizing.



**VAC —
ALERT™**
INDUSTRIES, LLC

*“Save a child’s life —
Vac-Alert™ saves lives.”*

www.vac-alert.com

For more information, contact Vac-Alert at 800-374-7405, or www.vac-alert.com.